

www.harscorail.com

SERVICE BULLETIN MAINTENANCE OF WAY EQUIPMENT

MAINTENANCE OF WAY EQUIPMENT					
DATE: 11-20	16			BULLETIN NO : 16-007	
TITLE: PD W	orkhead C	output Shaft Seal			
RATING:		DIRECTIVE (Action Is Required)		ALERT (Potential Problem)	
		INFORMATION (Action Is Optional)	X	PRODUCT IMPROVEMENT (Enhance Product)	
PRODUCT SI	ERIES / M	ODEL: Model 6700SJ2F (2011-Present)	PD Produ	ction and Switch Tampers	
SERIAL NO:	See list a	t the end of this Service E	Bulletin		
SUMMARY:	replacem workhead 2015 with seal leak pre-load	nent of PD Workhead On I Vibratory Assemblies (Ponthe the new two-piece seats. Although these workh	utput Sh D Workhold design dead vibras s not wor	rvice Bulletin SB15-015 regarding aft Seals. The positive displacement eads) manufactured since December continue to experience output shaft ators improved output shaft bearing king in the application. This Service ack to the original seal.	
	The excessive output shaft end play, and subsequent excessive radial movement of the output shaft is a root cause of the original seals leaking. This root cause has been addressed in PD Vibratory Assemblies manufactured since December 2015.				

OPERATIONAL IMPACT: The leaks do not impair tamping performance, however they are a nuisance, and in extreme cases can be an environmental issue.

ACTION: Seal Replacement

PD Vibrators manufactured from Dec 2015 to present:

Replace two-piece seal and flange with Seal and Flange per this Service Bulletin, and provided in Service Kit 5068441.

PD Vibrators manufactured from 2011 to Dec 2015:

- a) If original seal (Part No. L40550) is installed, leave as is replace as needed.
- b) If a PD Workhead seal has been replaced per Service Bulletin 15-015, Seal Kit 5060758, then replace the two-piece Seal and Flange with Seal and Flange per this Service Bulletin and provided in Service Kit 5068441.

Note: Once a PD Workhead Vibrator has been updated with the Seal and Flange per this Service Bulletin, only the seal (Part No. L40550) is required in the future.

ACTION: PD Workhead Rebuild

Many factors go into the decision of when to rebuild a Workhead, whether it is the entire Workhead Installation or only the PD Vibratory Assemblies. No-one parameter should be used to make this decision, and at least the following should be considered: overall condition of machine, operational intensity (regional versus production gang), operator experience, track conditions, quality and timing of periodic maintenance and servicing, etc.

During the life of a PD Vibratory Assembly – between rebuilds - periodic servicing will be required. This will include changing out the output seal, squeeze pin, and flanged bushings as required.

PD Vibrators manufactured from Dec 2015 onward -

Consider rebuilding when one or more of the following has occurred:

- a) 5 million insertions
- b) 5 years or seasons
- c) 7000 Machine (engine) hours.

PD Vibrators manufactured from 2011 to Dec 2015 -

Consider rebuilding when one or more of the following has occurred:

- a) 3 million insertions
- b) 4 years or seasons
- c) 4500 Machine (engine) hours.

Vibrators will be rebuilt to the latest design, which includes minimizing output shaft movement, and including the Seal and Flange described in this Service Bulletin.

CONTACT: Person: Kevin Hansen

Facility: Ludington, MI Phone: (231) 843-7435

E-Mail: khansen@harsco.com

SAFETY INFORMATION



■ FOLLOW APPLICABLE RAILROAD LOCKOUT - TAGOUT PROCEDURE TO DISABLE ENERGY SOURCES WHEN PERFORMING MAINTENANCE, MAKING ADJUSTMENTS OR REPAIRS TO THE EQUIPMENT. FAILURE TO HEED THIS WARNING COULD RESULT IN SEVERE BODILY INJURY.

OUTPUT SHAFT SEAL & SHAFT SEAL FLANGE REPLACEMENT PROCEDURE

- Be sure to follow the specific detail shown in Harsco Rail engineering drawing 5068441.
- Remove Tamping Tools from Tamping Tool Holder (use Removal Tool Harsco Rail p/n 5013208)
- 2. Remove Tamping Tool Holder from Output Shaft (use Removal Tool Harsco Rail p/n 5013205)
- 3. Remove old Seal Carrier Flange and O-Ring by first removing the four retaining bolts and sliding the Seal Carrier Flange (with seal) off the Output Shaft. Discard the removed items.
- 4. Remove old Speedi-Sleeve® if damaged in any way. Discard the removed items.
- 5. Install new Speedi-Sleeve® Harsco Rail p/n C4905Y03 that comes with the kit to the specified dimension on the drawing. Use Installation Tool Harsco Rail p/n 5068501.
- 6. Install the new Seal Harsco Rail p/n L40550 into the new Shaft Seal Flange Harsco Rail p/n 5068152 provided in the Kit.
- 7. Install the new Shaft Seal Flange (with seal) and O-Ring provided in Kit into the Vibratory Assembly using Permatex® Gasket Maker the four new bolts provided.
- 8. Install the Tool Holder on the Output Shaft.
- 9. Install the Tamping Tools.

5068441 - OUTPUT SHAFT SEALS & FLANGE KIT

ITEM	PART NO	DESCRIPTION	QTY
1	5068152	FLANGE, SHAFT SEAL	1
2	L40550	OIL SEAL (VIB)	1
3	150323-83	SNAP RING-INT, .109 THICK X 4.724 DIA	1
4	5007185	O-RING, 5.237 ID X .103 VITON	1
5	3564	SCREW-SHC, .25-20 X 1.00 LG	4
6	C4905Y03	SEAL, SPEEDI-SLEEVE	1

Recommended Special Tools (not included in 5068441 - Output Shaft Seal & Flange Kit)

5068501	Speedi-Sleeve Tool (Blue in color for identification)
	(for installing Speedi-Sleeve onto Shaft)
5013208	Removal Tool Assy, Tamp Tools
	(for removing Tamping Tools from Tamping Tool Holders)
5013205	Removal Tool Assy, Tool Holder
	(for removing Tamping Holder from Output Shafts)

Positive Displacement (PD) Workhead - Machine Build Record (as of November 2015)

Only Vibrators that were updated per Service Bulletin #SB15-015 on machines shown in Table 1 below require Service Kit 5068441 per this Service Bulletin.

Contact Harsco Rail, providing PD Vibrator Serial Number for warranty replacement of Seal and Flange.

TABLE 1
PD WORKHEAD MACHINES
MANUFACTURED IN LUDINGTON, MI

Customer/Railroad	Year	Machine Number	Machine Serial Number
CSX (FCM)	2011		153660
			153675
			153676
			153677
			153678
Alaska	2012	ET-20	153697
CP/Delta	2012		152625
Rebuild machines at			152733
Delta			152790
			152791
UPRR	2012	ATS-1201	153715
		ATS-1202	153716
		ATS-1203	153717
		ATS-1204	153718
KCS	2013		153734
KCS	2014		153751
UPRR	2014	ATS-1401	153778
		ATS-1402	153779
		ATS-1403	153780
		ATS-1404	153777
Relam	2014		153766
KCS	2015		153786
			153789
UPRR	2015	ATS-1501	153805
		ATS-1502	153806
		ATS-1503	153807
UPRR	2016	ATS-1601	153831 (*)
		ATS-1602	153832 (*)

(*) Requires Service Kit 5068441 per this Service Bulletin

Re-Manufactured Positive Displacement (PD) Workheads - (as of December 2015) (Machine Serial Numbers not known)

PD Workhead Vibrators used in re-manufacturing programs or as spares also fall under this service bulletin and require Service Kit 5068441. Machine Serial Numbers are not known.

All Vibrators listed in Tables 2-1 and 2-2 require Service Kit 5068441 per this Service Bulletin.

TABLE 2-1 INDIVIDUAL PD VIBRATORS USED FOR SPARES OR IN RE-MANUFACTURING PROGRAMS LISTED BY SERIAL NUMBER

Customer / Railroad	Build Completion Date	Vibrator Serial Number	Customer / Railroad	Build Completion Date	Vibrator Serial Number
0D/D I	15 D 0015	1=0.1=.1	11000	47 F L 2242	4=0.4=0
CP/Delta	15-Dec-2015	172154	UPRR	17-Feb-2016	172178
		172155			172179
		172156			172180
		172157			172181
		172158			172182
		172159			172183
		172160			172184
		172161			172185
OD/Dalta	45 Dag 0045	470400	LIDDD	00 Fab 0040	470400
CP/Delta	15-Dec-2015	172162	UPRR	26-Feb-2016	172186
		172163			172187
		172164			172188
		172165		_	172189
		172166			172190
		172167			172191
		172168			172192
		172169			172193
UPRR	21-Dec-2015	172170			172194
UPKK	Z 1-Dec-2015	172170	-	-	172194
				_	
		172172			172196
		172173			172197
		172174			172198
		172175			172199
		172176	-	-	173100
		172177			173101

TABLE 2-2 INDIVIDUAL PD VIBRATORS USED FOR SPARES OR IN RE-MANUFACTURING PROGRAMS LISTED BY SERIAL NUMBER

Customer / Railroad	Build Completion Date	Vibrator Serial Number	Customer / Railroad	Build Completion Date	Vibrator Serial Number
UPRR	15-Apr-2016	173102	UPRR	12-Apr-2016	173125
OI IXIX	10 / (p) 2010	173103	-	-	173126
	-	173104	_	25-Apr-2016	173127
	-	173105		20 / (p) 2010	173128
BNSF	15-Apr-2016	173106			173129
21101	10 / (5) 2010	173107		•	173130
	-	173108		•	173131
		173109			173132
UPRR	Phase 1	173110		-	173133
	-	173111		-	173134
	-	173112	BNSF	9-Jun-2016	173151
		173113	or Stock		173152
		173114	İ		173153
		173115			173154
		173116			173155
		173117			173156
-	-	173118	Ì		173157
		173119	UPRR	16-Jun-2016	173158
		173120	Ī		173159
		173121			173160
		173122	Ī		173161
		173123	Ī		173162
		173124	Ī		173163
					173164
					173165

© 2016 HARSCO CORPORATION, ALL RIGHTS RESERVED

415 North Main Street Fairmont, MN 56031-1837 Tel: (507) 235-3361

Tel: (507) 235-3361 Fax: (507) 235-7370 2401 Edmund Road, Box 20 Cayce-West Columbia, SC 29171-0020

Tel: (803) 822-9160 Fax: (803) 822-7471 Printed In USA 200 South Jackson Road Ludington, MI 49431 Tel: (231) 843-3431

Tel: (231) 843-3431 Fax: (231) 843-1644



