

## Harsco

www.harscotrack.com

# **SERVICE BULLETIN**

MAINTENANCE OF WAY EQUIPMENT					
DATE:	11-17-2003		BULLETIN NO:	03-026	
TITLE:	JACKING CYLINDER ROD EYE INTERFERENCE				
RATING:		<b>DIRECTIVE</b> (Action Is Required)		ALERT (Potential Problem)	
		INFORMATION (Action Is Optional)	X	PRODUCT IMPROVEME (Enhance Product)	≣NT
PRODUCT SERIES / MODEL: 6700S Tampers					
SERIAL NO:	All Models				
SUMMARY:	There have been several instances where the weld on the Jacking Cylinder rod eye can interfere with the boss on the Jackbeam Lifting ears. This interference usually occurs when the Jackbeam is all the way forward or rearward and the Jacking cylinder is completely retracted. When this condition exists, there is the possibility of putting a side load on the cylinder rod which can in turn cause premature wear to the cylinder barrel, piston and rod bearing. The interference can be eliminated by grinding a 3/4" x 45° chamfer on the top side of the Jackbeam Lifting Ear Boss.				
OPERATIONAL IMPACT: To improve jacking cylinder reliability and minimize wear					

To improve jacking cylinder reliability and minimize wear.

Grind a 3/4 inch x 45° chamfer on the top side of the Jackbeam Lifting Ear ACTION:

Boss per the instructions in this Service Bulletin.

CONTACT: If you have any questions or if we can be of any service, please contact Mark

Krusniak at the Ludington, MI. facility, (231) 843-3431.


#### SAFETY INFORMATION



■ FOLLOW APPLICABLE RAILROAD LOCKOUT - TAGOUT PROCEDURE TO REMOVE ALL ENERGY SOURCES FROM MACHINE. FAILURE TO COMPLY COULD RESULT IN SEVERE BODILY INJURY.

### JACKBEAM LIFTING EAR REWORK - See Figure 1

- 1. Lower the Jackbeam to the rail.
- 2. Remove the cylinder pin connecting the cylinder to the Jackbeam.
- 3. Swing the Jacking cylinder out of the way and secure to provide clearance for grinding.
- 4. Grind a 3/4 inch x 45° bevel on the top side of both Jackbeam cylinder ears as shown in Figure 1. Be sure to remove all sharp edges, burrs, etc.
- 5. Re-assemble the cylinder to the Jackbeam.
- 6. Repeat procedure to rework the Jackbeam lifting ears on the other side of the machine.



#### © 2003 HARSCO TRACK TECHNOLOGIES, HARSCO CORPORATION

415 North Main Street Fairmont, MN 56031-1837

Tel: (507) 235-3361 Fax: (507) 235-7370 2401 Edmund Road, Box 20 Cayce-West Columbia, SC 29171-0020

Tel: (803) 822-9160 Fax: (803) 822-7471 200 South Jackson Road Ludington, MI 49431

Tel: (231) 843-3431 Fax: (231) 843-1644

Printed In U.S.A.