

Harsco

www.harscotrack.com

SERVICE BULLETIN MAINTENANCE OF WAY EQUIPMENT

MAINTENANCE OF WAT EQUI MENT					
DATE:	2-28-2002	BULLETIN NO: 02	2-005		
TITLE:	2004976 CLAMP CYLINDER ROD SEAL AND WIPER SERVICE GROUP				
RATING:	DIRECTIVE (Action Is Required)	ALERT (Potential Problem)			
	INFORMATION (Action Is Optional)	X PRODUCT IMPROVEMENT (Enhance Product)			
PRODUCT SERIES / MODEL: 6700S Tamper					
SERIAL NO:	All Models Serial # 152700 thru 152	2990			
SUMMARY:	A new one-piece cylinder head incorporating a new design wiper and seal has been tested extensively and implemented at the Ludington, MI. facility for Clamp Cylinder part # 431499-1. The new rod seal and wiper are offered in a new one-piece Cylinder Head Assembly part # 2004976. This assembly replaces the original two-piece cylinder head.				

OPERATIONAL IMPACT: The one-piece cylinder head assembly will improve machine reliability and minimize leakage.

ACTION:

The installation of this Service Group requires:

- Removing the clamp cylinder from the machine.
- Dis-assembling the cylinder to remove the existing two-piece cylinder head, seals, o-rings, wiper, etc.
- Re-assembling the cylinder with the new one-piece cylinder head, seals, o-rings, wiper, etc.
- Re-installing the clamp cylinder on the machine.

CONTACT:

If you have any questions or if we can be of any service, please contact Bill Perry or Doug Budreau at the Ludington, MI. facility, (231) 843-3431.

SAFETY INFORMATION



■ FOLLOW APPLICABLE RAILROAD LOCKOUT - TAGOUT PROCEDURE TO REMOVE ALL ENERGY SOURCES FROM MACHINE. FAILURE TO COMPLY COULD RESULT IN SEVERE BODILY INJURY.

SERVICE GROUP INSTALLATION - See Figure 1, Figure 2 and Figure 3

- 1. Locate the clamp cylinder on the machine.
- 2. Disconnect the hydraulic lines from the clamp cylinder.

Note: Be sure to note which hydraulic lines are connected to the cylinder ports for proper re-assembly.


- 3. Remove the clamp cylinder from the machine.
- 4. Thoroughly clean the clamp cylinder. Then dis-assemble the clamp cylinder to remove the existing two-piece head, seals, o-rings, wiper, etc. as shown in Figure 1.
- 5. Re-assemble the clamp cylinder with the new one-piece head, seals, o-rings, wiper, etc. as shown in Figure 2 and Figure 3.

Note: Be sure to install the bearing joints at 180° from each other as shown in Figure 3.

- 6. Re-install the clamp cylinder on the machine.
- 7. Reconnect the hydraulic lines to the clamp cylinder.
- 8. Start the engine and pressurize the clamp cylinder circuit.
- 9. Check the clamp cylinder for hydraulic leaks.


SERVICE GROUP INSTALLATION





Α	170230-1	Cylinder Head 1	Ε	170231-1	Non-Extrusion Ring1
В	250444-1	Rod Seal 1	F	250443-1	Rod Wiper 1
С	150395-31	O-Ring1	G	150012-20	O-Ring1
D	155328-1	Back-Up Ring 1	Н	170232-1	Retainer Ring 1

FIGURE 2 1003775-2 CLAMP CYLINDER WITH NEW PARTS TO BE INSTALLED




1	2004240	Cylinder Head 1	5	150395-31	O-Ring
2	2004243	Rod Wiper 1	6	155328-1	Backing Ring 1
3	2004244	Rod Seal 1	7	150012-20	O-Ring1
4	2004245	Rod Bearing 2			

SERVICE GROUP INSTALLATION

1004382-1

FIGURE 3 **NEW CYLINDER HEAD ASSEMBLY**



SERVICE GROUP PARTS LIST

ITEM	PART NO	DESCRIPTION	QTY
	2004976	CYLINDER HEAD ASSEMBLY	1
1	2004240	Cylinder Head	1
2	2004243	Rod Wiper	1
3	2004244	Rod Seal	1
4	2004245	Rod Bearing	2
5	150395-31	O-Ring	1
6	155328-1	Backing Ring	1
7	150012-20	O-Ring	1

© 2002 HARSCO TRACK TECHNOLOGIES, HARSCO CORPORATION

415 North Main Street Fairmont, MN 56031-1837 Tel: (507) 235-3361 Fax: (507) 235-7370

2401 Edmund Road, Box 20 Cayce-West Columbia, SC 29171-0020 Tel: (803) 822-9160

Fax: (803) 822-7471

200 South Jackson Road Ludington, MI 49431

Tel: (231) 843-3431 Fax: (231) 843-4830

Printed In U.S.A.