

Harsco Track Technologies

Harsco

www.harscotrack.com

CEDVICE DITLICTIN

MAINTENANCE OF WAY EQUIPMENT					
DATE:	5-20-2005			BULLETIN NO:	05-005
TITLE:	VEHICLE 19-1/2" WHEEL INSPECTION				
RATING:	X	DIRECTIVE (Action Is Required)		ALERT (Potential Problem)	
		INFORMATION (Action Is Optional)		PRODUCT IMPROVEMI (Enhance Product)	≣NT
PRODUCT SE		ODEL: All Vehicles Equent using 19-1/2" Wheel M		ith HY-RAIL® Guide Wheen on Kits.	əl
SERIAL NO:	All 0307, HR0307A, HR1000, HR1200 and HR1500 Rail Pilot Unit Models				
SUMMARY:	HTT 19-1/2" wheel modification kits must be installed correctly, properly maintained, and inspected regularly. This will improve vehicle performance and also help to prevent and/or detect any problems with the wheels. Some vehicles have been misused and neglected which has led to wheel problems, such as rough ride and mechanical failure of the wheel. Cracks or breakage of the wheel have been reported in some cases. Rough ride may be attributed to poor tire quality or due to incorrect wheel / tire balancing techniques.				
OPERATIONA		T: To improve the funct diventibles.	ionality a	and safety of the HY-RAIL	B)
ACTION:	As a precaution, all vehicles equipped with the HTT 19-1/2" wheel modification kits should have all of their wheels inspected immediately, including the spare wheel. See the instructions on Page 2 of this Service Bulletin.				

CONTACT: If you have any questions or if we can be of any service, please contact the

appropriate HTT HY-RAIL® department at the Fairmont, MN. facility at the

phone numbers listed in Step 9 on Page 2 of this Service Bulletin:

SAFETY INFORMATION



n FOLLOW APPLICABLE RAILROAD LOCKOUT-TAGOUT PROCEDURE TO REMOVE ALL ENERGY SOURCES FROM VEHICLE AND RAIL GUIDE WHEEL EQUIPMENT. FAILURE TO COMPLY COULD RESULT IN SEVERE BODILY INJURY.

WHEEL INSPECTION INSTRUCTIONS

- 1. Thoroughly clean the entire wheel. Inspect the wheel for any type of damage that includes deformations, cracks, and/or breakage of any type.
- 2. Check the condition of the lug nuts. Check for proper torque as noted on the wheel decal. Replace any suspect lug nuts. Re-torque as required.
- 3. Confirm the actual weight of the vehicle. Weigh the vehicle on an accurate scale. Check the vehicle manufacturer's load ratings. Check the gross load rating plus each axle load rating. DO NOT EXCEED any of these ratings. Make adjustments to the payload if required.
- 4. If a rough ride is being reported, then check the balance of the wheels and tires. Replace the wheels or tires if they are suspected to be the problem.
- 5. If installing wheels due to a new installation, rebalancing, repair, or tire rotation, torque the lug nuts by the proper tightening procedure as outlined in the referenced Service Bulletins listed in Step 8 or in the Operator's Manual.
- 6. If any problems are discovered or questions arise, contact HTT at the phone numbers listed in Step 9.
- 7. HTT will replace any cracked or broken wheel under warranty if the vehicle has not been abused or over-loaded.
- 8. For reference, refer to the following previously issued HTT Service Bulletins concerning vehicle wheels. If you do not have a copy of these bulletins contact HTT at the phone numbers listed in Step 9.
 - 8.1 Service Data No. 559 dated 1-1991
 - 8.2 Service Bulletin No. 01-005 dated 7-2001
- 9. If you have any questions or if we can be of any service, please contact the appropriate HTT HY-RAIL® department at the Fairmont, MN. facility at the following phone numbers:
 - 9.1 Roger Kusick Service 507-235-7212 (office) or 803-315-9018 (cell)
 - 9.2 Roger Sanders Sales 507-235-7112 (office) or 803-767-8490 (cell)
 - 9.3 Julie Klages Sales 507-235-7191 (office)
 - 9.4 Neal Belgard Parts 507-235-7143 (office)

© 2005 HARSCO TRACK TECHNOLOGIES, HARSCO CORPORATION

415 North Main Street Fairmont, MN 56031-1837

Tel: (507) 235-3361 Fax: (507) 235-7370 2401 Edmund Road, Box 20 Cayce-West Columbia, SC 29171-0020

Tel: (803) 822-9160 Fax: (803) 822-7471 200 South Jackson Road Ludington, MI 49431

Tel: (231) 843-3431 Fax: (231) 843-1644