



www.harscorail.com

RAIL

SERVICE BULLETIN MAINTENANCE OF WAY EQUIPMENT

DATE: 5-31-2013 **BULLETIN NO:** 13-005

TITLE: BULLETIN #1558 - GRINDER MOTOR REPAIR PARTS LIST CORRECTION

RATING:

<input type="checkbox"/>	DIRECTIVE (Action Is Required)	<input type="checkbox"/>	ALERT (Potential Problem)
<input checked="" type="checkbox"/>	INFORMATION (Action Is Optional)	<input type="checkbox"/>	PRODUCT IMPROVEMENT (Enhance Product)

PRODUCT SERIES / MODEL: RGH10C2-36/37 RAIL GRINDERS - CHINA MOR #3 and UP

SERIAL NO: All of the Above Models

SUMMARY: There is an incorrect part number listed for the "Solenoid Valve Cartridge" on the repair parts list page of the #3400220 Grinder Motor Piping in the Hydraulic Components Section of the Parts Manual - Bulletin #1558 for the RGH10C2-36/37 Rail Grinders - China MOR #3 and Up. The correct part number for the Solenoid Valve Cartridge should be "409507" not "409407".

OPERATIONAL IMPACT: The incorrect part number results in the customer receiving an incorrect part when ordering this repair part number.

ACTION: Replace the existing #3400220 repair parts list page in Parts Manual - Bulletin #1558 with the corrected repair parts list page attached to this Service Bulletin.

CONTACT: If you have any questions or if we can be of any service, please contact:

Harsco Rail Service Department
Columbia, SC Facility
(803) 822-7546

UPDATING PARTS MANUAL - BULLETIN #1558

1. There is an incorrect part number listed for the "Solenoid Valve Cartridge" on the repair parts list page of the #3400220 Grinder Motor Piping in the Hydraulic Components Section of the Parts Manual - Bulletin #1558 for the RGH10C2-36/37 Rail Grinders - China MOR #3 and Up. The correct part number for the Solenoid Valve Cartridge should be "409507" not "409407".
2. Print out the corrected #3400220 Grinder Motor Piping repair parts list page attached to this Service Bulletin and punch holes to match your Parts Manual binder. Replace the existing #3400220 repair parts list page in the Hydraulic Components Section of your Parts Manual with the corrected repair parts list page.
3. If it is not possible to print out this corrected repair parts list page for your Parts Manual, then mark-up the existing repair parts list page in your Parts Manual with the correct part number to keep from ordering the wrong part number in the future.

© 2013 HARSCO CORPORATION, ALL RIGHTS RESERVED

415 North Main Street
Fairmont, MN
56031-1837
Tel: (507) 235-3361
Fax: (507) 235-7370

2401 Edmund Road, Box 20
Cayce-West Columbia, SC
29171-0020
Tel: (803) 822-9160
Fax: (803) 822-7471

200 South Jackson Road
Ludington, MI
49431
Tel: (231) 843-3431
Fax: (231) 843-1644

Printed In U.S.A.

3400220 GRINDER MOTOR PIPING

ITEM	PART NO	DESCRIPTION	QTY
80	414005	GRINDER MOTOR RELIEF MANIFOLD.....	2
	409507	Solenoid Cartridge Valve (Includes Seal Kit)	5
	3408784	Seal Kit - Solenoid Cartridge Valve.....	5
	409508	Replacement Coil - Solenoid Cartridge Valve	5
	409509	Cartridge Valve - Grinder Circuit	5
	409510	Cartridge Valve - Braking Circuit Relief.....	5
	416157	Pilot Spool - Between Relief Cartridge	5
	416149	Manifold	1

*Note: There Are Two Grinder Motor Relief Manifolds On Each Car.
The Quantities Listed Are For One Manifold Only.*

414005 GRINDER MOTOR RELIEF MANIFOLD

